## UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 6,972,247 B2

Page 1 of 1

APPLICATION NO.: 10/728519

**DATED** 

: December 6, 2005

INVENTOR(S)

: Stephen W. Bedell et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## Column 9,

Line 56, "3E16 cm<sup>-1</sup>." should read -- 3E16 cm<sup>-2</sup>. --.

## Column 10,

Line 3, "process of a spike anneal." should read -- process or a spike anneal --. Line 16, "process of a spike anneal" should read -- process or a spike anneal --.

## Column 12,

Line 32, "from about to about 500 nm" should read -- from about 10 to about 500 nm --.

Signed and Sealed this

Eleventh Day of July, 2006

JON W. DUDAS Director of the United States Patent and Trademark Office